

From: [Paul Duffield](#)
To: [Simon Adams](#)
Cc: [WHSQ Webmaster](#)
Subject: RTI request - Our ref: J0883
Date: Tuesday, 6 August 2019 9:20:13 AM
Attachments: [image001.png](#)
[image016.png](#)
[image017.png](#)

Hi Simon

The result is only four Incident Alerts between 1 November 2015 and 22 August 2017 to do with cranes or mobile elevated platforms.

They were:

Incident alert - Fatality - 23 November 2015 - Carole Park

OUR DISCLOSURE LOG

To ensure delivery to your inbox please add safe@justice.qld.gov.au to your address book.
Trouble viewing this email?, [read the online version](#).



Workplace Health and Safety Queensland is investigating a fatal incident that occurred on Monday 23 November 2015 at a workplace in Carole Park.

A worker was killed when he was run over by a crane that he was walking alongside.

Could this happen anywhere your employees are working?

This alert is a reminder for you and your organisation to consider the effectiveness of your safety management systems in preventing an incident like this from occurring at your workplace.

For information on workplace health and safety visit www.worksafe.qld.gov.au or call [1300 362 128](tel:1300362128).

Please note: Workplace Health and Safety Queensland cannot comment on the progress of individual investigations. Each workplace incident is different, so the time taken to complete a thorough investigation will vary depending on the circumstances. More complex incidents may take many months to complete.

Find us on:



MORE INFORMATION

- [Mobile plant](#)
- [Working in and around mobile plant](#)
- [Managing Risks of Plant in the Workplace Code of Practice 2013](#) (PDF, 1072 KB)
- [Mobile Crane Code of Practice 2006](#) (PDF, 1019 KB)
- [How to Manage Work Health and Safety Risks Code of Practice 2011](#) (PDF, 594KB)

CONTACT US



Queensland's Safety and Workers' Compensation Services
[1300 362 128](tel:1300362128)
[Enquire online](#)

[Subscribe](#) | [Unsubscribe](#) | [Update account](#) | [Privacy](#)



Incident alert - Fatality - 14 December 2015 - Newstead

To ensure delivery to your inbox please add safe@justice.qld.gov.au to your address book.
Trouble viewing this email?, [read the online version](#).



Workplace Health and Safety Queensland is investigating a fatal incident that happened on Monday 14 December 2015 in Newstead.

A photographer was killed and his son taken to hospital in a critical condition. Both were in the basket of an extended truck-mounted boom lift which fell over.

Could this happen anywhere your employees are working?

This alert is a reminder for you and your organisation to consider the effectiveness of your safety management systems in preventing an incident like this from occurring at your workplace.

For information on workplace health and safety visit www.worksafe.qld.gov.au or call 1300 362 128.

Please note: Workplace Health and Safety Queensland cannot comment on the progress of individual investigations. Each workplace incident is different, so the time taken to complete a thorough investigation will vary depending on the circumstances. More complex incidents may take many months to complete.

Find us on:



MORE INFORMATION

- [Managing the Risk of Falls at Workplaces Code of Practice 2011](#) (PDF, 1.8 MB)
- [Mobile Crane Code of Practice 2006](#) (PDF, 1.02 MB)
- [Film: Using elevating work platforms safely](#)
- [Construction industry](#)

CONTACT US



Queensland's Safety and
Workers' Compensation
Services
1300 362 128
[Enquire online](#)

Incident alert - Fatality - 3 March 2016 – Dalby



The Electrical Safety Office and Workplace Health and Safety Queensland are investigating a fatal incident that happened on Thursday 3 March 2016 near Dalby.

The operator of a tractor with a boom spray that had made contact with a high voltage powerline was killed. It appears that the contract worker had exited the tractor and made contact with the arm of the boom spray and the ground at the time of the incident.

Could this happen anywhere your employees are working?

This alert is a reminder for you and your organisation to consider the effectiveness of your safety management systems in preventing an incident like this from occurring at your workplace.

For electrical safety information visit www.electricalsafety.qld.gov.au or call 1300 362 128.

Please note: Workplace Health and Safety Queensland and the Electrical Safety Office cannot comment on the progress of individual investigations. Each workplace incident is different, so the time taken to complete a thorough investigation will vary depending on the circumstances. More complex incidents may take many months to complete.

FIND US ON:



MORE INFORMATION

- [Electrical hazards](#)
- [Working near energised electrical parts](#)

CONTACT US



Office of Industrial Relations
1300 362 128

[Enquire online](#)

[Subscribe](#) | [Unsubscribe](#) | [Update account](#) | [Privacy](#)



To ensure delivery to your inbox please add safe@justice.qld.gov.au to your address book.
Having trouble viewing this email? [View Online](#)



Workplace Health and Safety Queensland is investigating a serious incident that happened on Tuesday 7 June 2016 at a work site on Grey Street, South Brisbane. A 100 tonne mobile crane fell over and its fly struck a building. No-one was injured.

Please note we are not able to comment on the progress of an investigation. Each incident is different, and the time taken to complete a thorough investigation will vary with the circumstances.

Could this happen anywhere your employees are working?

This alert is to remind you and your organisation that if you are planning to operate a crane with partially extended outriggers, you must verify the acceptability of the loading configuration from the manufacturer's load charts. The load chart shows the allowable lifting capacities of the crane when set up with the outriggers partially extended and must be complied with. Additionally, set-up and pack-up of any crane must be completed in accordance with procedures specified by the manufacturer.

More information

For information on workplace health and safety visit [our website](#) or call 1300 362 128.

FIND US ON:



MORE INFORMATION

- [Mobile Crane Code of Practice](#) (PDF, 1019 KB)
- [Safe operation of mobile cranes](#) (PDF, 227 KB)
- [Checklist - planning the safe set-up and operation of mobile cranes](#) (DOCX, 39 KB)

CONTACT US



Queensland's Safety and
Workers' Compensation
Services
1300 362 128

[Enquire online](#)

I hope this helps.

Thanks and regards
Paul

Paul Duffield

A/Principal Online Services Officer, Awareness and Engagement
Office of Industrial Relations

M sch.4/3/3 Personal

From: Simon Adams

Sent: Monday, 5 August 2019 9:16 AM